2024 Report on South Dakota Bridges



Data from NBI Submittal in March 2024

The South Dakota DOT owns 1819 bridge length (> 20 ft.) structures. Local government agencies (counties, cities, other governmental agencies, townships) own 3932 structures. Of the 1819 state owned structures, there are 1239 bridges and 580 culverts. Of the 3932 LGA structures, there are 2905 bridges and 1027 culverts.


The 1239 state owned bridges account for 10,811,222 sq. ft of deck area and the 2905 locally owned bridges account for 7,026,237 sq. ft of deck area. The average state-owned bridge was built in 1977 and is approximately 41 ft wide by 211 ft long.


There are 9 major Missouri River highway bridge crossings in South Dakota. Two are maintained by Nebraska DOT, and seven are maintained by South Dakota. The seven structures managed by South Dakota total 914,420 sq ft of deck area. This is approximately 8.6% of the state-owned bridge deck area. Four of these bridges are in the Mitchell Region and the other three are in the Pierre Region. The Nebraska DOT manages the bridges on the SD 37 crossing at Running Water and the US 81 crossing at Yankton.

The average Missouri River Bridge is approximately 3,355 feet long. The longest bridge in the state is the Platte-Winner Bridge on SD 44 over Lake Francis Case Reservoir and is 5,656 feet long.


Recent SDDOT Bridge Condition Trends

Currently 1.9% or 35 structures in the SDDOT bridge inventory are in poor condition. In 2018 the requirements that cause a bridge to be structurally deficient changed. Now the definitions for poor condition and structurally deficient are identical.





2



Most bridges in the state are inspected every two years. South Dakota received approval from FHWA based upon 23 CFR 650 to inspect some of the bridges every 4 years. Currently there are 561 structures eligible for 4-year inspections. All major Missouri River bridge crossings the SDDOT manages are inspected every year, except the SD 19 bridge over the Missouri River which was built in 2001. Bridges that require underwater inspections are inspected every 5 years by an underwater inspection consultant who inspects the underwater portions of the bridge. Underwater inspections were conducted on the Missouri River bridges in 2022. The remainder of the bridges that require underwater inspections completed in 2023.

Frequency	Bridges	NBI Culverts	Total
12 months	66	0	66
24 months	979	213	1192
48 months	194	367	561
Total	1239	580	1819

Inspection Frequency of State Structures

Miscellaneous Statistics

	Bridges	NBI Culverts	Total
On Interstate System	580	54	634
On Interstate Mainline	401	43	444
Structures over Water	769	570	1339

Border Bridge Details

Highway	Feature Intersected	Border Agency	SD Str Number	Border State Structure Number	State that Maintains Inventory
I 29 N	Big Sioux River	lowa	64-165-405	00000000053930	South Dakota
I 29 S	Big Sioux River	lowa	64-164-405	00000000053941	South Dakota
SD 50	Big Sioux River	lowa	64-086-223	00000000039650	Iowa
SD 48	Big Sioux River	City of Akron	64-122-170	00000000603911	South Dakota
SD 46	Big Sioux River	lowa	64-160-023	00000000048451	Iowa
US 18	Big Sioux River	lowa	42-201-136	0000000034481	lowa
SD 19	Missouri River	Nebraska	14-104-249	00000S015 20985	South Dakota
SD 37	Missouri River	Nebraska	05-090-279	00000S014 20330	Nebraska
US 81	Missouri River	Nebraska	68-120-210	00000S081 21489	Nebraska